

**LAKE ROSALIND WELL 3
REHABILITATION AND
WELL 1 TESTING**

Prepared for:

**THE CORPORATION OF THE
MUNICIPALITY OF BROCKTON**

Mail: P.O. Box 451, Paris ON N3L 3T5
Office: 92 Scott Avenue, Paris ON N3L 3R1
Phone: (519) 442-2086
Fax: (519) 442-7242



Date: December 19, 2018

Reference: 248-026

THE CORPORATION OF THE MUNICIPALITY OF BROCKTON

**LAKE ROSALIND WELL 3 REHABILITATION
AND WELL 1 TESTING**

	<u>Page</u>
BACKGROUND	1
WELL 3 PRE-REHABILITATION TESTING	2
WELL 3 PRE-REHABILITATION VIDEO SURVEY	2
WELL 3 REHABILITATION	3
WELL 3 POST-REHABILITATION VIDEO SURVEY	4
WELL 3 CASING THICKNESS AND CALIPER LOGS	5
WELL 3 PUMP INSTALLATION	5
WELL 3 POST-REHABILITATION TESTING	5
WELL 1 TESTING	6
WELL 1 AND 3 PUMPING AND LEVEL HISTORY	6
IMPORTANT OBSERVATIONS	7
RECOMMENDATIONS	8

TABLES

1	Well 3 Pre-Rehabilitation Variable Rate Performance Test
2	Well 3 Pre-Rehabilitation Static Video Summary
3	Well 3 Post-Rehabilitation Static Video Summary
4	Well 3 Post-Rehabilitation Variable Rate Performance Test

FIGURES

1	Well 3 Comparison of Variable Rate Tests
2	Well 3 Casing Thickness and Caliper Log

- 3 Well 3 Pump Installation Drawing
- 4 Well 1 Well Construction Drawing
- 5 Well 1 Flow and Level Summary
- 6 Well 3 Flow and Level Summary

APPENDICES

- A Water Well Record
- B Well Disinfection Record



P.O. Box 451
Paris, ON N3L 3T5

92 Scott Avenue
Paris, ON N3L 3R1
T (519) 442-2086
T (800) 923-6923
F (519) 442 7242
www.lotowater.com

December 19, 2018

Reference: 248-026

Veolia North America
130 Wallace St.
Walkerton, Ontario
N0G 2V0
Box 220

Attention: Scott Gowan, Project Manager, Veolia North America

**SUBJECT: LAKE ROSALIND WELL 3 REHABILITATION
AND WELL 1 TESTING**

This report documents the work performed by Lotowater Technical Services Inc. (LTS) at Lake Rosalind Wells 1 and 3. The service program for Well 3 included well performance testing, video survey, pumping equipment replacement and well rehabilitation. The field work was performed over several days from November 28-30, 2018. Lotowater has worked at both wells in the past, starting in 2003, but has very limited information on the wells prior to this.

BACKGROUND

Lake Rosalind Well 3 is a 200 mm diameter drilled well, believed to be constructed in 1987 (see attached well record in **Appendix A**). The well is constructed with a 200 mm steel casing set to a depth of 15.5 m with a 150 mm diameter screen set in overburden from 15.84-18.92 m. The well penetrates a clay aquitard from roughly 11-13 m. The well was found equipped with a 10gpm and ½ horsepower motor installed in 2005. The well was last video inspected and serviced in 2005, at which time a new ½ horsepower submersible pump was installed. Well 3 has experienced periods where the levels have drawn down near the pump inlet, which has required pumping to be reduced to avoid pump cavitation. This has occurred several times in 2003, 2005, & 2007. In these cases, flows were made up by increasing pumping at Well 1.

Lake Rosalind Well 1 is a 1.0 m diameter dug well which is 4.12 m deep. No construction or MOE well record could be located for this well. The well is equipped with a 38 mm HDPE suction line and foot valve with a ½ horsepower jet pump and motor located in the pump house. This well has high artesian water levels and regularly flows to waste out a screened overflow when well levels are high. The well was last tested and inspected when repairs were made to the suction line and well tiles in 2011. Well 1 levels have fluctuated, but levels have never been low enough to cavitate the pump since at least 2003. The well reportedly has more issues with bacteria hits than Well 3, and for this reason, is used to supplement Well 3.


Both wells feed the plant which filters the incoming raw water through a bag filter system, then through a contact chamber and eventually into and underground reservoir. From there, submersible high lift pumps distribute to the Lake Rosalind distribution system, which services 60 residents along Lake Rosalind Road #4. Both wells operate simultaneously, with Well 3 operating at approximately 0.7 L/s and Well 1 at 0.3 L/s when the reservoir calls for water based on reservoir level. The average Lake Rosalind system demand has ranged from 15-30 m³/day over recent years with roughly 70% of the flow from Well 3 and the remaining 30% from Well 1.

WELL 3 PRE-REHABILITATION TESTING

A pre-rehabilitation well step test was conducted on November 28, 2018. The data collected is provided in **Table 1** and was plotted graphically and compared against historical pumping levels on **Figure 1**. Static levels are well above levels measured during the last step test in 2003. Drawdowns, however, appear similar and indicate no significant loss in well performance due to plugging.

WELL 3 PRE-REHABILITATION VIDEO SURVEY

A pre-rehabilitation static video was completed November 28, 2018, with significant well construction details noted in **Table 2**. A DVD copy of the video has been enclosed with the original hard copy of this report. The video showed significant fouling of the casing and screen with debris filling the bottom of the well (**Photos 1 to 4**).






Photo 3: Buildup on Casing




Photo 4: Buildup on Casing

WELL 3 REHABILITATION

The well rehabilitation was performed to remove the buildup on the screen and casing. The rehabilitation program utilized a dual tube airlift assembly and high pressure jetting system. The well was initially airlifted off bottom using a 50 mm x 10 mm dual airlift to remove sediment and debris in preparation of the jetting. After the initial airlift, the well was jetted with a high pressure rotating head jetting tool. The tool was raised and lowered over the casing and screen while jetting at 7,500psi @ 1.0 L/s, while simultaneously airlifting the well at a 1.0 L/s rate to remove material dislodged during jetting. The well was jetted and airlifted in this manner for two hours and produced a dark red to reddish brown discharge with some fine silt and sand. After the jetting, the well was airlifted off bottom until the discharge was clear and sediment free. Some photos of the rehabilitation setup and equipment are shown in (**Photos 5 to 8**).



Photo 5: Set up on Well



Photo 6: Jetting Tool



Photo 7: Airlift Discharge



Photo 8: Interior of Video/Logging Van

WELL 3 POST-REHABILITATION VIDEO SURVEY

A post-rehabilitation video was completed November 29, 2018, with significant well construction details noted in **Table 3**. A DVD copy of the video has been enclosed with the original hard copy of this report. The video showed the well screen had been successfully cleaned and the debris noted in the previous video removed (**Photos 9 to 11**). The video inspection identified a hole in the well casing following cleaning as shown in **Photo 12**. There were no indications of any leaking or sediment entering the well through the hole during the video.





Photo 9: Clean Well Screen



Photo 10: Bottom of Well



WELL 3 CASING THICKNESS AND CALIPER LOGS

A casing thickness log was completed November 29, 2018. The results of the log are presented as **Figure 2** and show some variability in overall casing thickness, but no overall signs of thinning. Note however, the casing thickness log did not identify the small hole in the casing; as the log was outside resolution of the thickness tool.

A three arm caliper log was also run, which indicated a 200 mm nominal diameter casing which appears to decrease slightly in diameter with depth. At the k-packer and screen, the diameter decreases significantly to 159 mm interior diameter.

WELL 3 PUMP INSTALLATION

Lotowater installed a new pump, motor and HDPE discharge piping on November 29, 2018. In addition, a new stinger for the pitless adapter was cut and threaded then installed on top of the pitless adapter. A pump installation drawing has been included as **Figure 3**, and a well disinfection record has been included in **Appendix B**. Testing of the pump was performed after installation, which showed it performing satisfactorily. In addition, testing also indicated that there are no significant leaks or plugging of the line that connects the well to the plant.

WELL 3 POST-REHABILITATION TESTING

A post-rehabilitation well performance test was conducted on November 30, 2018. The data collected is provided in **Table 4** and was plotted graphically and compared against historical pumping levels on **Figure 1**. The post-rehabilitation test results indicated a similar performance when compared to the pre-rehabilitation data. The well is more than capable of producing the normal operating flow rate in the short term. The testing indicates that there is no significant plugging of the well screen.

WELL 1 TESTING

A data logging pressure transducer was installed in Well 1 to log the levels in Well 1 while Well 3 was off line for maintenance. Levels are plotted on **Figure 2**. Over the three days Well 1 was off, Well 3 averaged about 18 m³/day. The well came on 4 times over this period and levels drew down from a high on Nov 28 of 0.71 m to a low of 0.97 m. The well recovered quickly and levels were well above the pump inlet (at 3.39 m) the entire time. Well 1 well drawing showing basic construction details was created and shown on **Figure 4**.

A brief test was performed to assess the existing Myers HJ50S-K jet pump performance with details as follows.

Flow	= 0.29 L/s
Pressure	= 42 psi
Amps	= 5.1
Well Level	= 0.71 m
TDH	= 33 m

The pump appears to be operating properly and close to its operating curve.

WELL 1 AND 3 PUMPING AND LEVEL HISTORY

Average monthly pumping rates and weekly well levels were plotted at each well starting in 2003. Well levels are collected manually by Veolia staff. These plots are shown in **Figures 5 and 6**. Total pumping appears to average 15-25m³/day over the last several years.

Well 1 levels fluctuated from 0.4 - 2.9 m over the past 15 years with levels generally not going below 2.0 m, except for July of 2017. It appears that levels are generally lowest in the summer and highest in the early spring. Well levels don't necessarily correlate with pumping as there are times with increased pumping and high water levels in the spring on 2016. Conversely, there was a period of no pumping in the spring and summer of 2007 where levels were low. Although pumping may be a contributing factor to Well 1 level declines, it appears that there are other factors that have a more significant impact on levels. These could be due to changes in precipitation, recharge or pumping from other nearby wells.

Well 3 had extreme fluctuations of levels over the same 15 year period. Levels have been very near the well head such that the well was nearly overflowing to as low as the pump inlet at 17.1 m. Levels appear to be the lowest in late fall to early winter, and highest in spring. Years of low well levels where the pump was likely cavitating, were in 2003, 2005 & 2007. Similar to Well 1, low levels in the well don't always correlate to high periods of pumping, and there are likely other factors that are contributing to these severe level declines. Over the last 7 years, well levels have never approached the pump inlet.

IMPORTANT OBSERVATIONS

Well 3 was successfully rehabilitated and new pumping equipment installed. Some additional conclusions and observations for Well 3 are as follows:

- Pre rehabilitation performance testing showed well performance was similar to the last performance test in 2003, and that, despite the buildup seen on the screen, plugging was not having a significant impact on the wells performance.
- Pre inspection video showed corrosion and buildup covering the screen and casing which was removed by rehabilitation.
- The post rehabilitation video identified a hole in the casing, but there were no obvious signs of leaking water, sand or sediment entering through the hole.
- The casing thickness log showed no overall casing thinning. The hole is believed to be isolated to one small spot of the casing, which is outside the resolution of the casing thickness tool, so it was not seen in the casing thickness log.
- Post rehabilitation testing showed similar performance to the pre rehabilitation testing. The well can easily be pumped up to its equipped capacity, at least for the short term.
- Plugging of the well screen here is not a significant contributor to historic low water levels in this well.
- Long term review of level and pumping history shows that levels in the well can change relatively quickly, even drawing levels down to the pump, and reasons for this are not clear. Increased seasonal pumping from the well is likely contributing to these declines, but other factors such as precipitation, recharge and potentially, pumping from other nearby wells, are likely having significant impacts as well.
- Over the last 7 years the current use appears sustainable with levels maintained well above the pump inlet.

No service or maintenance was performed at Well 1. However, testing showed that the well levels were well above the pump inlet at the normal current pumping rate. In addition, the existing pump was found to be performing satisfactorily. Some additional conclusions and observations for Well 1 are as follows:

- Well 1 levels fluctuate but have never reached the pump inlet like at Well 3.
- Well 1 had a period of low levels recently in July of 2017 and the cause of this is not clear.
- Long term review of level and pumping history doesn't show a strong correlation with pumping and well levels. Levels appear more affected by other factors, such as precipitation and recharge.

- Over at least the last 15 years, the current use appears sustainable with levels maintained well above the pump inlet.
- Despite periods of low levels in either Well 1 or 3, these low levels never occurred at the same time. This is a good sign that the wells are not significantly interconnected and that if one well is experiencing low levels the other appears capable to meet increased pumping demands.

RECOMMENDATIONS

It appears the system has been working over the last 5 plus years with no significant issues. However, Lotowater recommends the following actions be considered to increase the reliability and security of the wells.

- Install a new stainless steel liner in Well 3 to repair the hole in the well casing. At the same time, raise the well casing and ground level to facilitate easier access and maintenance.
- If levels drop below 2.5 m in Well 1, and levels are above 13 m in Well 3, decrease pumping at Well 1 by 50% and increase pumping correspondingly at Well 3 to make up the difference. Return to the existing pumping configuration when levels in Well 1 recover to 2.0m.
- If levels drop below 12 m in Well 3, and levels are above 2.5 m in Well 1, decrease pumping at Well 3 by 50% and increase pumping correspondingly at Well 1 to make up the difference. Return to the existing pumping configuration when levels in Well 3 recover to 10.0m.
- Establish a warning criteria for different levels of water conservation based on well levels. This could include a yellow level warning to conserve, if water levels in Well 1 drop below 2.5 m or if water levels in Well 3 drop below 13 m. A red level warning would be if both Well 1 and Well 3 drop below 2.5 and 13 m correspondingly, which would instigate a higher level of conservation.
- Consider automating level collection at Well 1 and 3 using self-contained data logging transducers such as a Solonist Level Troll or van Essen Diver. Have the well log on a daily basis and download annually.
- Consider installing remote well level readouts in the pump house so operators can easily check well levels and optimize pumping schemes to balance pumping between the two wells as described above.
- Update the well level hydrographs and pumping history plots annually and have a hydrologist and/or groundwater professional review and comment.

It has been a pleasure working with Veolia and the Municipality of Brockton on this project. Please contact the undersigned if you require further information.

Yours sincerely,
Lotowater Technical Services Inc.

A handwritten signature in black ink, appearing to read 'B. Pendleton', with a stylized flourish at the end.

Boyd Pendleton, B. Sc., P. Geo.
Vice President

TABLES

TABLE 1

VARIABLE RATE PERFORMANCE TEST

Pre-Rehabilitation

Well Name: Lake Rosalind Well 3

Client: Municipality of Brockton

Technician Name: Craig Lawson

Water Level Device: LTS water level meter

Water Level Reference: Top of casing

Test Note: Top of sounding tube = 0.97 m above ground surface

Project Number: 248-026

Date: 2018-11-28

Pump: Client's

Pump Inlet: 17.1 mbtc

Flow Measuring Device: Clients meter

[illegible]

TABLE 2**Municipality of Brockton**

**Lake Rosalind Well 3
Pre-Rehabilitation Static Video Summary
2018/11/28**

Elapsed Time (h:min)	Depth (ft below MP)	Depth (m below MP)	Comments
0:00	2.76	0.84	Below top of casing
0:01	6.99	2.13	Pitless adapter
0:04	17.72	5.40	Casing joint
0:04	17.72	5.40	Static water level
0:06	29.53	9.00	Pause, set sample pump to clear image
Chapter 2			
0:00	29.49	8.99	Below top of casing
0:02	37.27	11.36	Casing joint
0:05	49.70	15.15	K-Packer
0:06	51.90	15.82	Top of screen
0:08	59.74	18.21	Bottom of well, sediment
0:14	51.84	15.80	Top of screen
0:17	50.16	15.29	K-Packer
0:24	37.24	11.35	Casing joint
0:30	23.75	7.24	Water level
0:32	17.98	5.48	Casing joint
0:36	6.89	2.10	Pitless adapter
0:38	2.53	0.77	Below top of casing
<p align="center">Video survey conducted by Jason Dion</p> <p align="center">Note: Measuring point (MP) is top of casing which is 0.83 m above ground surface</p>			

TABLE 3**Municipality of Brockton**

Lake Rosalind Well 3
Post-Rehabilitation Static Video Summary
2018/11/29

Elapsed Time (h:min)	Depth (ft below MP)	Depth (m below MP)	Comments
0:00	2.76	0.84	Below top of casing
0:00	6.89	2.10	Pitless adapter
0:02	17.39	5.30	Casing joint
0:02	23.39	7.13	Static water level
0:10	29.53	9.00	Pause, set sample pump to clear image
0:13	36.42	11.10	Casing joint
0:16	49.54	15.10	K-Packer
0:17	51.84	15.80	Top of screen
0:20	62.07	18.92	Bottom of well, sediment
0:29	51.97	15.84	Top of screen
0:31	50.36	15.35	K-Packer?
0:32	49.87	15.20	K-Packer?
0:36	45.51	13.87	Possible hole in casing
0:40	37.40	11.40	Casing joint
0:48	23.79	7.25	Water level
0:51	18.18	5.54	Casing joint
0:56	7.05	2.15	Pitless adapter
0:59	2.79	0.85	Below top of casing
<p align="center">Video survey conducted by Jason Dion</p> <p align="center">Note: Measuring point (MP) is top of casing which is 0.83 m above ground surface</p>			

TABLE 4

VARIABLE RATE PERFORMANCE TEST

Post-Rehabilitation





Well Name:	Lake Rosalind Well 3
Client:	Municipality of Brockton
Technician Name:	Craig Lawson
Water Level Device:	LTS water level meter
Water Level Reference:	Top of casing
Test Note:	Top of sounding tube = 0.97 m ab

Project Number:	248-026
Date:	2018-11-30
Pump:	Client's
Pump Inlet:	17.1 mbtc
Measuring Device:	Clients meter

Test Note: Top of sounding tube = 0.97 m above ground surface

[illegible]

FIGURES



Notes:

All water levels are referenced from top of sounding tube
 Top of casing = 0.97 m above ground surface

MUNICIPALITY OF BROCKTON

LAKE ROSALIND WELL 3

Comparison of Variable Rate Tests

Lotowater Technical Services Inc.

Reference: 248-026


Figure 1

2018-12-13


Figure 2

Client: Municipality Of Brockton
Well Name: Well 3
Location: Lake Roslind
Project No: 248-026

Measuring Point: TOC
Measuring Point Elev: 0.84m ags
Logged By: J. Dion
Logging Date: November 30, 2018



Depth in Metres



CLIENT


MUNICIPALITY OF BROCKTON

TITLE

LAKE ROSALIND WELL 3
PUMP INSTALLATION DRAWING

PROJECT #: 248-026			G:\Lotowater Projects\248 Municipality of Brockton\ Lake Roalind Well 3.dwg		
DESIGN			REVISION No. Dec 18, 2018	SCALE N.T.S	FIGURE 3
DRAWN	BP	2018/12/13			
CHECKED	.	.			

Depth in Metres



CLIENT

MUNICIPALITY OF BROCKTON

TITLE

LAKE ROSALIND WELL 1
INSTALLATION DRAWING

PROJECT #: 248-026

G:\Lotowater Projects\248 Municipality of Brockton\ Lake Roalind Well 1.dwg

DESIGN

REVISION No.

SCALE

FIGURE

DRAWN

BP

2018/12/13

Dec 18, 2018


N.T.S

4

CHECKED

.

.



Notes:

Levels referenced to meters below sound tube port

MUNICIPALITY OF BROCKTON

LAKE ROSALIND WELL 1


Well 1 Hydrograph vs Daily Pumping

Lotowater Technical Services Inc.

Reference: 248-026

Figure 5

2018-12-18



Notes:

Levels referenced to meters below sounding tube port

MUNICIPALITY OF BROCKTON

LAKE ROSALIND WELL 3

Well 3 Hydrograph vs Daily Pumping

Lotowater Technical Services Inc.

Reference: 248-026

Figure 6

18/12/2018

APPENDICES

APPENDIX A

Water Well Record



Lake Rosalind Well 3

The Ontario Water Resources Act

WATER WELL RECORD

1. PRINT ONLY IN SPACES PROVIDED
2. CHECK ☒ CORRECT BOX WHERE APPLICABLE

11

1406588

MUNICIP
14004

CON.
DR N

03

COUNTY OR DISTRICT		TOWNSHIP, BOROUGH, CITY, TOWN, VILLAGE		CON., BLOCK, TRACT, SURVEY, ETC.		LOT	
Bruce		Brant Twp.		Con. 3 N.D.R.		67	
OWNER (SURNAME FIRST)		ADDRESS		DATE COMPLETED			
TOWNSHIP OF BRANT		R.R. 1, Elmwood, Ontario. N0G 1S0		DAY 23 MO Apr. YR 87.			

21 17 495560 4890555 RC 0950 RC BASIN CODE

LOG OF OVERBURDEN AND BEDROCK MATERIALS (SEE INSTRUCTIONS)

GENERAL COLOUR	MOST COMMON MATERIAL	OTHER MATERIALS	GENERAL DESCRIPTION	DEPTH - FEET	
				FROM	TO
Brown	Fine sand	Silt	Soft	0	8
Brown	Medium sand		Soft	8	10
Brown	Fine sand	Silt	Soft	10	23
Brown	Medium sand		Soft	23	39
Brown	Clay	Silt	Soft	39	44
Brown	Medium sand		Soft	44	58
Brown	Medium sand	Silt	Soft	58	71
Grey	Clay	Silt	Soft	71	75

4		WATER RECORD			
WATER FOUND AT - FEET		KIND OF WATER			
48 ¹⁰⁻¹³ 60	1	<input checked="" type="checkbox"/> FRESH	3	<input type="checkbox"/> SULPHUR	12
	2	<input type="checkbox"/> SALTY	4	<input type="checkbox"/> MINERAL	
15-18	1	<input type="checkbox"/> FRESH	3	<input type="checkbox"/> SULPHUR	19
	2	<input type="checkbox"/> SALTY	4	<input type="checkbox"/> MINERAL	
20-23	1	<input type="checkbox"/> FRESH	3	<input type="checkbox"/> SULPHUR	24
	2	<input type="checkbox"/> SALTY	4	<input type="checkbox"/> MINERAL	
25-28	1	<input type="checkbox"/> FRESH	3	<input type="checkbox"/> SULPHUR	29
	2	<input type="checkbox"/> SALTY	4	<input type="checkbox"/> MINERAL	
30-33	1	<input type="checkbox"/> FRESH	3	<input type="checkbox"/> SULPHUR	34
	2	<input type="checkbox"/> SALTY	4	<input type="checkbox"/> MINERAL	

CASING & OPEN HOLE RECORD				
INSIDE DIAM INCHES	MATERIAL	WALL THICKNESS INCHES	DEPTH - FEET	
			FROM	TO
10-15	<input checked="" type="checkbox"/> STEEL <input type="checkbox"/> GALVANIZED <input type="checkbox"/> CONCRETE <input type="checkbox"/> OPEN HOLE	.250	0	48
17-18	<input type="checkbox"/> STEEL <input type="checkbox"/> GALVANIZED <input type="checkbox"/> CONCRETE <input type="checkbox"/> OPEN HOLE			20-23
24-25	<input type="checkbox"/> STEEL <input type="checkbox"/> GALVANIZED <input type="checkbox"/> CONCRETE <input type="checkbox"/> OPEN HOLE			27-30

SCREEN	SIZE: 5" OF OPENING (SLOT NO.)	31-33	DIAMETER	34-38	LENGTH	39-40
	10" x 18 slot 10" x 6 slot		7.75	INCHES	12.67	FEET
	MATERIAL AND FINISH		DEPTH TO TOP OF SCREEN	41-44	INCHES	10
	Stainless Steel		47.33		FEET	
	Telescope					

61 PLUGGING & SEALING RECORD			
DEPTH SET AT - FEET		MATERIAL AND TYPE (CEMENT GROUT, LEAD PACKER, ETC.)	
FROM	TO		
10-13	14-17	Sand Fill	
60	75		
18-21	22-25		
26-29	30-33	30	

PUMPING TEST	PUMPING TEST METHOD		PUMPING RATE		DURATION OF PUMPING	
	1 <input checked="" type="checkbox"/> PUMP 2 <input type="checkbox"/> BAILER		70 Imp GPM		48 15-18 HOURS 17-18 MINS	
	STATIC LEVEL		WATER LEVEL END OF PUMPING		25 1 <input type="checkbox"/> PUMPING 2 <input type="checkbox"/> RECOVERY	
	19-21		22-24		15 MINUTES 30 MINUTES 45 MINUTES 60 MINUTES	
	0.9 FEET		26-28 FEET		29-31 FEET 32-34 FEET 35-37 FEET	
	IF FLOWING, GIVE RATE		PUMP INTAKE SET AT		WATER AT END OF TEST	
38.61 GPM		46 FEET		1 <input checked="" type="checkbox"/> CLEAR 2 <input type="checkbox"/> CLOUDY		
RECOMMENDED PUMP TYPE		RECOMMENDED PUMP SETTING		RECOMMENDED PUMPING RATE		
<input type="checkbox"/> SHALLOW <input type="checkbox"/> DEEP		43-45 FEET		46-49 GPM		
50-53						

FINAL STATUS OF WELL	54	1 <input checked="" type="checkbox"/> WATER SUPPLY	5 <input type="checkbox"/> ABANDONED, INSUFFICIENT SUPPLY
		2 <input type="checkbox"/> OBSERVATION WELL	6 <input type="checkbox"/> ABANDONED POOR QUALITY
		3 <input type="checkbox"/> TEST HOLE	7 <input type="checkbox"/> UNFINISHED
		4 <input type="checkbox"/> RECHARGE WELL	
WATER USE	55-56	1 <input type="checkbox"/> DOMESTIC	5 <input type="checkbox"/> COMMERCIAL
		2 <input type="checkbox"/> STOCK	6 <input checked="" type="checkbox"/> MUNICIPAL
		3 <input type="checkbox"/> IRRIGATION	7 <input type="checkbox"/> PUBLIC SUPPLY
		4 <input type="checkbox"/> INDUSTRIAL	8 <input type="checkbox"/> COOLING OR AIR CONDITIONING
		<input type="checkbox"/> OTHER _____	<input type="checkbox"/> NOT USED
METHOD OF DRILLING		1 <input type="checkbox"/> CABLE TOOL	5 <input type="checkbox"/> BORING
		2 <input checked="" type="checkbox"/> ROTARY (CONVENTIONAL)	6 <input type="checkbox"/> DIAMOND
		3 <input type="checkbox"/> ROTARY (REVERSE)	7 <input type="checkbox"/> JETTING
		4 <input type="checkbox"/> ROTARY (AIR)	8 <input type="checkbox"/> DRIVING
		5 <input type="checkbox"/> AIR PERCUSSION	

LOCATION OF WELL

IN DIAGRAM BELOW SHOW DISTANCES OF WELL FROM ROAD AND LOT LINE. INDICATE NORTH BY ARROW.

8" WELL 20' →


25'

LAKE ROSALIND RD #4

LAKE ROSALIND

06924

DRILLERS REMARKS:

CONTRACTOR	NAME OF WELL CONTRACTOR		LICENCE NUMBER	
	Davidson Well Drilling Limited		1737	
	ADDRESS			
	Box 486, Wingham, Ontario. N0G 2W0			
	NAME OF DRILLER OR BORER		LICENCE NUMBER	
	G. Reavie		T0156	
	SIGNATURE OF CONTRACTOR		SUBMISSION DATE	
			DAY <u>7</u> MO. <u>May</u> YR. <u>87</u>	

OFFICE USE ONLY	DATE SUBMIT	CONTRACT NO.	AGE	DATE RECEIVED	AGE
	JUL 10 1987				
	DATE OF INSPECTION 12/8/88	INVESTIGATOR			
	REMARKS APL CSS.SS				

APPENDIX B

Well Disinfection Record

APPENDIX B

Well Chlorination Record

Well Name: Lake Rosalind Well 3
Client: Municipality of Brockton
Project #: 248-026
Disinfected By: Craig Lawson

LTS Chlorination Worksheet Used: Yes
Treatment Volume: 428 Litres
Desired Concentration: 150 ppm
Volume of Mixing Water: N/A Litres
Qty of Sterilene Needed (granular 55%): 116.75 grams

Type and Quantity of Chlorine Used: Sterilene 115 g
Date and Time Chlorine Added: 2018-11-29 15:20

Chlorine Residual Measured at Surface: 150 ppm
Chlorine Residual Measurement Method: Test strip

Date & Time Chlorine Purged: 2018-11-29 9:00
Pre-Purge Chlorine Residual Measured at Surface: 100 ppm
Chlorine Residual Measurement Method: Test strip
Purged By: Craig Lawson
Purged To: Waste
Quantity and Type of Dechlorinating Agent Used: Chlor-Oust
Minutes of Pumping until Zero Free Chlorine Residual: 30 minutes
Final Turbidity Measurement (NTU): N/A
Notes on Disinfection: Recirculated to flush chlorine