

Prepared By:




Municipality of Brockton

2018 – Greenock Structure No. 0013 OSIM

Our File: 216137

June 2019





BRIDGE REVIEW REPORT

Structure No.: 0013
MTO Site No.: N/A
Location: Lot 23A, Concession 8, Greenock Survey
Date of Review: May 31, 2019
Inspector: Jesse Borges, B. Eng., EIT
Estimated Safe Loading: No posting required.

Structure Description:

Structure:	Cast-in-place concrete arch culvert	Year Constructed:	unknown
No. Spans:	1	Width:	±16.5m
		Length:	±6.5m
Approaches:	Asphalt		
Wearing Surface:	Asphalt		
BCI:	22		

Remarks:

- Asphalt wearing surface is in fair to poor condition with longitudinal and transverse cracks. Asphalt at north has been patched.
- There is a steel beam guiderail on the structure and off the approaches.
- Several guiderail posts and bearing blocks are damaged in the southwest and northeast approaches.
- The southeast retaining wall is not part of the structure but does have severe deterioration and water leaking. Failure of the following wall could cause problems for the culvert.
- There is no headwall on either side of the culvert. It appears that part of the ground behind the southwest corner has slumped in and the grade is eroding due to water runoff on the steep slope.
- There is a large stone wingwall in the southwest corner. There is no mortar between the stones.
- There is no drip edge cast into the soffit.
- There is a medium horizontal crack along the width of the structure at each construction joint. There is also light honeycombing along the length of the construction joints.
- There are numerous hairline to medium longitudinal and transverse cracks throughout the structure with efflorescence indicating water is leaking through the entire structure.
- There is some spalling at the south soffit and the northwest wall exposing reinforcing steel.
- South embankment is failing, causing the guiderail to be pulled down and away from the roadway.
- The large vegetation growing beside and on top of the barrel will allow roots to damage the structure.

Conclusions:

Generally, the structure appears in fair to poor condition. There is excessive cracking throughout the structure covered with efflorescence indicating water is leaking through the structure. However, the structure does appear to be stable. Waterproofing the top of the arch and refacing the interior surface of the barrel may extend the life span of the structure. However, performing major repairs to the structure would only delay the structures replacement and would not be financially beneficial to the Municipality. The structure has been recommended for replacement since 2010 when it was introduced into the Brockton Review Program indicating construction by 2020. An intrusive investigation in 2012 exposed a portion of the exterior surface of the barrel which exhibited sound concrete in fair condition.

The rate of deterioration from 2010 to 2019 has been slower than expected allowing the Municipality to delay the replacement of the structure. The Municipality should prepare for replacement of this structure within 1 -5 years.

Recommendations:

1. Continue to monitor condition of soffit with reviews every two years.
2. Budget for replacement in 1 to 5 years.

GM BLUEPLAN ENGINEERING LIMITED

Per:

A handwritten signature in blue ink, appearing to read 'J. Borges', is written over a horizontal line.

Jesse Borges, B.Eng., E.I.T.



Inventory Data:

Structure Name	Greenock Bridge Structure No. 0013		
Main Hwy/Road #	<input type="text"/>	On <input checked="" type="checkbox"/> Under <input type="checkbox"/>	Crossing Type: Navig. Water <input type="checkbox"/> Non-Navig. Water <input checked="" type="checkbox"/> Rail <input type="checkbox"/> Road <input type="checkbox"/> Ped. <input type="checkbox"/> Other <input type="checkbox"/>
Road Name	Chepstow Road/Concession Road 6		
Structure Location	0.1Km East of Side Road 5		
Latitude	<input type="text" value="44.15426"/>	Longitude	<input type="text" value="-81.27508"/>
Owner(s)	<input type="text" value="Municipality of Brockton"/>	Heritage Designation:	Not Cons. <input checked="" type="checkbox"/> Cons./not App. <input type="checkbox"/> List/not Desig. <input type="checkbox"/> Desig./not List <input type="checkbox"/> Desig. & List <input type="checkbox"/>
MTO Region *	<input type="text" value="South Western"/>	Road Class:	Freeway <input type="checkbox"/> Arterial <input type="checkbox"/> Collector <input type="checkbox"/> Local <input checked="" type="checkbox"/>
MTO District *	<input type="text" value="Owen Sound"/>	Posted Speed	<input type="text" value="50 Km/hr"/> No. of Lanes <input type="text" value="2"/>
Old County *	<input type="text" value="Greenock"/>	AADT	<input type="text"/> % Trucks <input type="text"/>
Geographic Twp. *	<input type="text" value="Brockton"/>	Special Routes:	Transit <input type="checkbox"/> Truck <input type="checkbox"/> School <input type="checkbox"/> Bicycle <input type="checkbox"/>
Structure Type *	<input type="text" value="Arch Culvert"/>	Detour Length Around Bridge	<input type="text"/> (km)
Total Deck Length	<input type="text" value="9.60"/> (m)	Fill on Structure	<input type="text" value="+1.0"/> (m)
Overall Str. Width	<input type="text" value="22.20"/> (m)	Skew Angle	<input type="text" value="20"/> (Degrees)
Total Deck Area	<input type="text" value="213.20"/> (sq.m)	Direction of Structure	<input type="text" value="N-S"/>
Roadway Width	<input type="text" value="6.90"/> (m)	No. of Spans	<input type="text" value="1"/> (m)
Span Lengths	<input type="text" value="8.60m"/> (m)		

Historical Data:

Year Built	<input type="text" value="Unknown"/>	Year of Last Major Rehab.	<input type="text"/>
Last OSIM Inspection	<input type="text" value="Unknown"/>	Last Evaluation	<input type="text"/>
Last Enhanced OSIM Inspection	<input type="text"/>	Current Load Limit	<input type="text" value="/ /"/> (tonnes)
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="text"/>	Load Limit By-Law #	<input type="text"/>
Last Underwater Inspection	<input type="text"/>	By-Law Expiry Date	<input type="text"/>
Last Condition Survey	<input type="text" value="2012"/>	Min. Vertical Clearance	<input type="text"/> (m)

Rehab. History: (Date/description)

An intrusive investigation completed in 2012 exposed a portion of the exterior soffit surface of the barrel which exhibited sound concrete in fair condition.

Field Inspection Information:			
Date of Inspection:	May 31, 2019	Type of Inspection:	X OSIM <input type="checkbox"/> Enhanced OSIM
Inspector:	Jesse Borges, B.Eng., EIT		
Others in Party:	Trevor O'Brien, P.Eng.		
Access Equipment Used:	Camera, Measuring Tape and Hammer		
Weather:	Sunny		
Temperature:	+16 °C		

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Material Condition Survey					
	Detailed Deck Condition Survey:	X			
	Non-destructive Delam. Survey of Asphalt-Covered Deck:	X			
	Concrete Substructure Condition Survey:	X			
	Detailed Coating Condition Survey:	X			
	Detailed Timber Investigation	X			
	Post-Tensioned Strand Investigation	X			
Underwater Investigation:		X			
Fatigue Investigation:		X			
Seismic Investigation:		X			
Structure Evaluation:		X			
Monitoring (deformations, settlements, movements, crack widths)		X			
Load Posting – Estimated Load		Total Cost			
Investigation Notes:					

Overall Structure Notes:		Replacement in 1-5 Years.
Overall Comments:	Generally, the structure appears to be in fair to poor condition. The barrel of the structure has active signs of water seepage through the concrete arch with efflorescence and corrosion staining. Spalls were noted throughout the barrel with exposed reinforcing exhibiting severe section loss. The steep embankments at the four quadrants of the structure are showing signs of erosion. Erosion of the embankments and over the culvert have caused the steel beam guiderail to rotate away from the roadway. We recommend that the structure be replaced in 1-5 years.	
Date of Next Inspection:	May 31, 2021	

Suspected Performance Deficiencies

01	Load carrying capacity	06	Bearing not uniformly loaded/unstable	12	Slippery surfaces
02	Excessive deformations (deflections & rotations)	07	Jammed expansion joint	13	Flooding/channel blockage
03	Continuing settlement	08	Pedestrian/vehicular hazard	14	Undermining of foundation
04	Continuing movements	09	Rough riding surface	15	Unstable embankments
05	Seized bearings	10	Surface ponding	16	Other
		11	Deck drainage		

Maintenance Needs

01	Lift and Swing Bridge Maintenance	07	Repair to Structural Steel	13	Erosion Control at Bridges
02	Bridge Cleaning	08	Repair of Bridge Concrete	14	Concrete Sealing
03	Bridge Handrail Maintenance	09	Repair of Bridge Timber	15	Rout and Seal
04	Painting Steel Bridge Structures	10	Bailey bridges - Maintenance	16	Bridge Deck Drainage
05	Bridge Deck Joint Repair	11	Animal/Pest Control	17	Scaling (Loose Concrete or ACR Steel)
06	Bridge Bearing Maintenance	12	Bridge Surface Repair	18	Other

Element Data

Element Group:*	Culvert	Length:	22.20m		
Element Name: *	Barrel	Width:	8.60m		
Location:		Height:	4.40m		
Material: *	Cast-In-Place Concrete	Count:	1		
Element Type: *	Arch	Total Quantity:	305.0		
Environment:	Benign / Moderate / Severe	Limited Inspection	<input type="checkbox"/>		
Protection System: *			Perform. Deficiencies		
Condition	Units	Exc.	Good	Fair	Poor*
Data:	m ² / m / each / % / all			183.0	122.0
Comments: Concrete barrel exhibiting significant signs of water penetration with efflorescence deposits. Concrete spalls noted with exposed corroded reinforcing. Active water leakage noted at construction joints. Vertical and horizontal narrow to medium cracks noted with efflorescence.					
Recommended Work:			Maintenance Needs:		
<input type="checkbox"/> Rehab <input checked="" type="checkbox"/> Replace <input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years <input type="checkbox"/> None Replace culvert structure.			<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:*	Deck	Length:	21.60m		
Element Name: *	Wearing Surface	Width:	6.90m		
Location:		Height:			
Material: *	Asphalt	Count:	1		
Element Type: *		Total Quantity:	149.10		
Environment:	Benign / Moderate / Severe	Limited Inspection	<input type="checkbox"/>		
Protection System: *			Perform. Deficiencies		
Condition	Units	Exc.	Good	Fair	Poor*
Data:	m ² / m / each / % / all		59.10	45	45
Comments: Transverse cracks noted over structure. Rutting and map cracking noted at edge of roadway over structure. Asphalt patch noted from previous investigation.					
Recommended Work:			Maintenance Needs:		
<input type="checkbox"/> Rehab <input checked="" type="checkbox"/> Replace <input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years <input type="checkbox"/> None Replace asphalt wearing surface.			15 <input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 year <input type="checkbox"/> 2 year Rout and seal asphalt.		

Element Group:*	Retaining Wall	Length:	4.30m		
Element Name: *		Width:	0.30m		
Location:	Southeast Quadrant	Height:	2.30m		
Material: *	Mass Concrete	Count:	1		
Element Type: *		Total Quantity:	9.89		
Environment:	Benign / Moderate / Severe	Limited Inspection	<input type="checkbox"/>		
Protection System: *			Perform. Deficiencies		
Condition	Units	Exc.	Good	Fair	Poor*
Data:	m ² / m / each / % / all			2.0	7.89
Comments: Retaining wall is in poor condition with severe concrete deterioration, scouring and spalling.					
Recommended Work:			Maintenance Needs:		
<input type="checkbox"/> Rehab <input checked="" type="checkbox"/> Replace <input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years <input type="checkbox"/> None Replace retaining wall.			<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

* A quantity must be estimated using the appropriate unit (e.g. m²). Percent should not be used

Element Data

Element Group:*	Barrier	Length:	95.0m			
Element Name: *	Barriers/Parapet Walls	Width:				
Location:		Height:				
Material: *	Steel	Count:	1.0			
Element Type: *	Steel Flex Beam on Wood Posts	Total Quantity:	95.0			
Environment:	Benign / Moderate / Severe	Limited Inspection	<input type="checkbox"/>			
Protection System: *	Hot Dip Galvanizing					
Condition	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies
Data:	m ² / m / each / % / all			31.0	64.0	02
Comments: North and south guiderail have rotated outward away from roadway due to possible erosion issues on embankment. All wood posts are exhibiting signs of rot and deterioration. Localized guiderail damage at southwest, northwest and northeast due to vehicle impact.						
Recommended Work: <input type="checkbox"/> Rehab <input checked="" type="checkbox"/> Replace <input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years <input type="checkbox"/> None Replace guiderail system.				Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:*	Foundations	Length:				
Element Name: *	Foundation (Below Ground Level)	Width:				
Location:		Height:				
Material: *	Cast-in-Place Concrete	Count:	1			
Element Type: *	Spread Footing	Total Quantity:	1			
Environment:	Benign / Moderate / Severe	Limited Inspection	<input checked="" type="checkbox"/>			
Protection System: *						
Condition	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies
Data:	m ² / m / each / % / all	N/A	N/A	N/A	N/A	
Comments: Limited inspection due to water and granular elevation. Footing at southwest corner exposed. Concrete curb poured in past to stop granular scouring at southwest corner. Based on overall condition of structure, foundation appears to be performing.						
Recommended Work: <input type="checkbox"/> Rehab <input checked="" type="checkbox"/> Replace <input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years <input type="checkbox"/> None Replace foundation with culvert.				Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:*	Embankments and Streams	Length:				
Element Name: *	Embankments	Width:				
Location:	Each Quadrant	Height:				
Material: *	Earth	Count:	4			
Element Type: *		Total Quantity:	4			
Environment:	Benign / Moderate / Severe	Limited Inspection	<input type="checkbox"/>			
Protection System: *						
Condition	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies
Data:	m ² / m / each / % / all		3	1		
Comments: Embankments appear to be in good to fair condition. Holes in southwest embankment noted due to erosion and water infiltration. All embankments appear to be overly steep but stable. Large trees and heavy vegetation growing on both sides of roadway over structure.						
Recommended Work: <input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years <input type="checkbox"/> None Remove large vegetation and stabilize embankments.				Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

* A quantity must be estimated using the appropriate unit (e.g. m²). Percent should not be used

Element Data

Element Group:*	Embankments and Streams		Length:			
Element Name: *	Streams and Waterways		Width:			
Location:			Height:			
Material: *			Count:			
Element Type: *			Total Quantity:			
Environment:	Benign / Moderate / Severe		Limited Inspection	<input type="checkbox"/>		
Protection System: *						Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	m ² / m / each / % / all		1			
Comments: Watercourse is clear of debris and appears to be flowing without any obstructions. Turbulence at southwest corner of structure has scoured culvert foundations in past. Water depth during inspection varied with south end of structure at 0.9m and north end of structure at 0.2m.						
Recommended Work: <input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years <input type="checkbox"/> None Install scour protection in watercourse after culvert replacement.			Maintenance Needs:			
			<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			

* A quantity must be estimated using the appropriate unit (e.g. m²). Percent should not be used.

Repair and Rehabilitation Required:		Priority				Estimated Structural Cost
Element ¹	Repair and Rehabilitation Required ²	6 to 10 years	1 to 5 years	Within 1 year	Urgent	
Culvert	Replacement		X			\$500,000
Asphalt	Replacement		X			\$25,000
Sidewalk/Curb	Replacement		X			\$15,000
Barrier	Replacement		X			\$25,000
Foundations	Replacement		X			\$350,000
Retaining Wall	Replacement		X			\$10,000
Stream/Waterway	Rehabilitation		X			\$10,000
Other	Structure Demolition		X			\$120,000
Estimated Rehabilitated or Replacement Structure Dimensions ³		Total Structural Cost				\$1,055,000
Total Deck Length (m)						
	Overall Str. Width (m)					

1 - Indicate specific costs for structure replacement OR for rehabilitation under the given headings.

2 - Give a very brief description of the rehabilitation work required.

3 - Estimated structure dimensions after completion of the proposed work – if it is expected to change.

Associated Work ⁴ :	Comments	Estimated Associated Work Cost
Approaches ⁵		
Detours		
Traffic Control		\$20,000
Utilities		
Other (Dewatering)		\$50,000
Environmental Assessment		\$100,000
Engineering	Engineering Design and Contract Administration (15%)	\$170,000
Contingency	(15%)	\$170,000
Total Associated Work Cost		\$510,000

Total Construction Cost	\$1,565,000
-------------------------	--------------------

4 - Includes other construction costs associated with the structure. Engineering fees for reports, environmental studies, designs, project management and contingencies are not included as associated work and should be specified on the Building Canada Fund – Communities Component (BCF-CC) Bridge Technical Schedule.

5 - Approach cost is for work (fill, pavement, guide rail, etc.) immediately adjacent to the structure to adjust for minor changes in horizontal or vertical alignment and for barrier end treatments at the structure. For BFC-CC applications, approaches longer than 30m (per end) require a separate Local Road Infrastructure Technical Schedule to be completed for that portion of road.

Justification:
<p>The structure is nearing the end of its useful life cycle. The structure is exhibiting overall deterioration with active water seepage. We recommend the structure be replaced in 1-5 years.</p>

BRIDGE INSPECTION REPORT– 2019

MUNICIPALITY OF BROCKTON

Structure No. 0013



Photo 1 - View of south elevation.



Photo 2 - View of roadway looking west.

BRIDGE INSPECTION REPORT– 2019

MUNICIPALITY OF BROCKTON

Structure No. 0013



Photo 3 - View of north elevation.



Photo 4 - Typical transverse crack in asphalt.

BRIDGE INSPECTION REPORT– 2019

MUNICIPALITY OF BROCKTON

Structure No. 0013



Photo 5 - Settlement and cracking of asphalt along southern edge of wearing surface.



Photo 6 - Outward rotation of south steel beam guiderail.

BRIDGE INSPECTION REPORT– 2019

MUNICIPALITY OF BROCKTON

Structure No. 0013



Photo 7 - View of typical rotted post.



Photo 8 - Deteriorated retaining wall at southeast.

BRIDGE INSPECTION REPORT– 2019

MUNICIPALITY OF BROCKTON

Structure No. 0013



Photo 9 - View of typical soffit condition.



Photo 10 - Evidence of water seepage through original construction joints.

BRIDGE INSPECTION REPORT– 2019
MUNICIPALITY OF BROCKTON

Structure No. 0013



Photo 11 - Barrel wall with exposed reinforcing.



Photo 12 - Active water seepage through barrel wall.

BRIDGE INSPECTION REPORT- 2019

MUNICIPALITY OF BROCKTON

Structure No. 0013



Photo 13 - Exposed reinforcing with severe section loss.



Photo 14 - Top of foundation exposed at southwest.

BRIDGE INSPECTION REPORT– 2019

MUNICIPALITY OF BROCKTON

Structure No. 0013



Photo 15 - Large vegetation (tree) growing on top of culvert.



Photo 16 - Voids at southwest embankment due to erosion.

BRIDGE INSPECTION REPORT– 2019

MUNICIPALITY OF BROCKTON

Structure No. 0013



Photo 17 - View of watercourse looking north.



Photo 18 - View of watercourse looking south.