


Municipality of Brockton - Recreation 290 Durham St.W, Walkerton N0G 2V0 ON 519-881-0625

Playground Inspection Form - Monthly

Information	
(no label)	
Walkerton Community Centre	
Tuesday, April 18th 2023, 1:45 PM (EDT -04:00)	
General Site Information	
Date of Inspection	April 18, 2023
Time of Inspection	1:35 PM
Person Completing Inspection	Mitch Rapp
Playground Inspected	
Elmwood Community Center	
Components Present	
Composite Play Structure, Swings - Belt, Swings - Tot, See-Saw	vs, Surfacing
Type of Surfacing Material	
Wood Chips	
Inspection	
Equipment Stability and Broken/Lose components	
Re-Distribute loose fill surfacing material to areas o	of "dishing" (ie. Slide exits, overhead components etc.)
Check depth of protective surfacing to ensure adeq	յսасу (minimum 3 locations)
Not enough protective surfacing or none at all	



✓ X NA	Check all moving components for maintenance concerns	
✓ X NA	Check condition of site furnishings and site amenities for vandalism	
⊗ ⊗ NA	Check any wood components for cracking, splitting, splintering and gaps greater than 19mm (3/4")	
⊗ ⊗ NA	Check condition of retaining wall/barrier (if present)	
✓ X NA	Check condition of access into play area (ie. pathway, fencing, etc.)	
Ø ⊗ NA	Check all fittings, bearing hangers, guardrails and componenents	
✓ X NA	Check swing seats for damage and decay	
✓ X NA	Check swing chains for kinked, twisted or broken chains	
✓ X NA	Check slides for cracks and sharp points	
✓ X NA	Check tires for drainage and/or protruding steel components	
✓ X NA	Check for graffiti and/or vandalism	
⊗ ⊗ NA	Check for components requiring monitoring and/or repair from previous monthly or annual inspection report (ie. has situation deteriorated? Was repair made? and if so is it now compliant or has a new problem been created?)	
✓ ✓ NA	Check for seasonal or environmental issues (ie. gaps at slides created by expanding or shrinking components such as poly slides, sectional slides becoming disjointed, Lexan Panels warping, frost heave, etc.)	
✓ ✓ NA	Check for exposed foundations (i.e. concrete footings and other connecting devices, etc.)	
✓ X NA	Remove any obvious hazards	
	Check for drainage problems/issues	
Surfacing Maintenance Information		
Approximate time frame for top-up of protective surfacing		
As soon as possible		
Approximate time frame for Rotor-tilling/loosening of protective surfacing		
Not applicable		
Overall Comments		
Issues requiring immediate attention:		
Top up surface before opening play structure		
Person contacted regarding above noted issue(s): — No Response		
Additional Comments		
■ No Response		
Signatures		

Mitch Rapp, Facility Attendant



April 18th 2023, 1:45 PM (EDT -04:00)



44.2405043, -81.0673581